





Trax Seating System Assembly Instructions




General Information



1. Beam
2. Leg
3. Armrest
4. Back Assembly
5. Seat Assembly
6. M8 X 30mm Button Head MachineScrew
7. M8 x 25mm CSK Machine Screw

Step 1: Place beam supports




Note: Beam supports are optional, if not supplied simply place beam on the floor.

- *Place protective covering on floor.*
- *Position beam supports.*

Parts Required:

1 x Protective Covering
2 x Beam Supports

Step 2: Place beam on supports





- *Place beam on supports with leg holes facing upwards (see next stage).*

Note: Orientate beam so that 'OMK DESIGN LONDON' logo is upside down.

Parts Required:

1 x Beam

Step 3: Attach legs



Note: Use holes 2 and 3 when mounting a table onto end of beam.



- Position legs so that the four holes align with the outermost corresponding holes [1 and 2] on the beam ends [see detail].
- Attach with 4 x M8 x 30mm button head machine screws.

Note: Use holes 2 and 3 when mounting a table onto end of beam.

Parts Required [per leg]:

1 x Leg
4 x M8 x 30mm Button Head Machine Screw

Step 4: Attach armrests





- Flip beam on to legs.
- Orientate arms so that the longer side faces forward, corresponding to the longer end of the legs.
- Position armrests along the beam as shown in the above diagram.
- Attach each armrest with 2 x M8 x 25mm CSK machine screws.

Parts Required [per armrest]:

- 1 x Armrest
- 2 x M8 x 25mm CSK Machine Screws

Step 5: Attach back assembly





- *Attach back assemblies with 4 x M8 x 30mm button head machine screws.*
- *Repeat process down the beam.*

Parts Required [per back assembly]:

1 x Back Assembly
4 x M8 x 30mm Button Head Machine Screws

Step 6: Attach seat assembly




- Place a raised support on the floor [eg: box], and tilt unit backwards until the front face of the beam is horizontal.
- Attach seat assemblies with 4 x M8 x 30mm button head machine screws.
- Repeat process down the beam.

Parts Required [per seat assembly]:



1 x Seat Assembly
4 x M8 x 30mm Button Head Machine Screws

Optional Step: Attach table and bracket

1



2



M8 Alpha Screw
M8 Lock Washer
M8 Nut

- Attach table bracket to beam using 2 x M8 x 25mm CSK machine screws.
- Attach table to bracket using 4 x M8 x 30mm alpha screws, 4 x M8 lock washers, and 4 x M8 nuts.

Parts Required [per table]:

1 x Table
1 x Table Bracket
2 x M8 x 25mm CSK Machine Screw
4 x M8 x 30mm Alpha Screw
4 x M8 Lock Washer
4 x M8 Nut

Contact Us

Our head office is located in central London where we manage global sales, design & production.

OMK Design Ltd.
30 Gresse Street
London, W1T 1QR
United Kingdom

enquiries@omkdesign.com

+44 (0)207 631 1335

